

Menu

HISTORY FILE MAP for year 1999

Realtime

Playback


Recalled Realtime

Recalled Playback

5m RT plus 38m PB degraded 45%.
Heavy rain at DSS42. No DR.

11m RT gap - TGC problems at
DSS42 during BRC from 512 to
1K. DR A03966.

10m RT lost - U/L freq glitch due to procedural
error at DSS42. Ground Rx lost lock, but s/c
remained 2-way. DR A03964.



16m RT lost at DSS34. Probs with 2-way to
1-way & BRC from 1K to 4K. DR A03979.

15m RT gap. TGC probs during BRC from
1K to 512 at DSS42. DR A03974.